Open-File Report
89-329
Figure 10a

Prepared in cooperation with
the U.S. Department of Energy



Figure 10a.--Lithologic and density logs obtained in holes in northern N-tunnel area. (See fig. 2 for explanation of stratigraphy)