


**Figure 3.** Altitude of the water table in the Biscayne aquifer and location of observation wells, surface-water structures, and major well fields in Dade County, May 5, 1993.




**Figure 4.** Altitude of the water table in the Biscayne aquifer and location of observation wells, surface-water structures, and major well fields in Dade County, November 2, 1993.

TRENDS IN WATER-TABLE ALTITUDE (1984-93) AND SALTWATER INTRUSION (1974-93) IN THE BISCAYNE AQUIFER, DADE COUNTY, FLORIDA

By
Roy S. Sonenshein and Edward J. Koszalka

1996