Gravity Corer Deck Log

SESAR IGSN #: __ECS003000___

USGS ID: H-3-10-AR

Coast Guard ID: HLY1002

Date/Time 11 Aug 2010

Latitude 71° 19.06

Longitude 143° 59.897

Wire Out 2487 / 2400

Weight Stand

Purpose Pierce ment strat L125 L977AR

Depth 2530

Number of Barrels 1

Pull Out 7110

Static 6500

Target Pt _71°19.08'N, -144°00.0'W__

Observer TDE

Gravity Core

Core ID 1GB1

Max Recovery

Mud Line

Cut Points

240

S1	☑	Section 1
S2	☑	Section 2
S3	☐	Section 3
S4	☐	Section 4
CA	☐	Core Catcher
CC	☑	Core Cutter
MFx	☑	Microfauna (ext)
GG	☐	Gas (geochem)
	☐	

Catcher (CA)

Cutter(CC)

Sh vs in H_2O 2130z

Sea state 5'

wind 060° ~ 20 kts

hit @ 100 m/min

hold 2 min @ bt

Brief Textural Description

Other Comments Test various wire rates 80, 100, 100+

2500 1300 3800

4000 2400 6500

Piston Corer Deck Log
(2500 lb)

SESAR IGSN #: ECS 003001 3002

USGS ID: H-3-10-AR

Coast Guard ID: HLY1002

Date/Time 3:15:30

Latitude 71 19.048

Longitude 143 59.982

Wire Out 2465

Scope 16'

Purpose Piercement Structure L-e725 L977AR

Depth 2538

Observer ITDE

in H_2O ~1915 Load Pullout 8750 Base Tens~ 46200

Piston Core

Core ID IP-1 ECS-3001

Max Recovery 571cm

Mud Line

20ft

Cut Points

0 D 12cm

121 C 150

271 B 150

421 A 150

571

many cracks

GAP 464 to 522

Catcher (CA)

Cutter(CC)

- S1 ☑ Section 1 0-121
- S2 ☑ Section 2 121-271
- S3 ☑ Section 3 271-421
- S4 ☑ Section 4 421-571
- S5 ☐ ~~Section 5~~
- S6 ☐ ~~Section 6~~
- CA ☑ Core Catcher 2bags
- CC ☑ Core Cutter (HYDRATE) now gone
- MFx ☑ Microfauna (ext)
- GG ☑ Gas (geochem)

Photo ☑ of gas hydrate in cc

Gas hydrate in core cutter CC undamaged

Lower sections fractured by apparent gas, numerous voids throughout

Measurements on deck from bottom of section

B Gap in core 121-123cm

Strong Gas Odor

☑ MFsurface

Wire kinked when 9/16 wire slacked & trigger arm struck bucket. Wire retorminated. Pull test required.

Trigger Core ECS 3002

Core ID LTC-1

Max Recovery 83cm

Mud Line

Cut Points

- S1 ☑ Section 1
- ~~S2 ☐ Section 2~~
- CA ☑ Core Catcher
- CC ☑ Core Cutter
- MFx ☑ Microfauna (ext)

Catcher (CA)

Cutter(CC)

Trigger core over penetrated surface sediment blown out of top of core

Brief Textural Description

ice band @ bow - beginning to come along side

Other Comments

payout @ btm 20m/min

Deck forgot to put water in barrel @ deployment

after tx for of 9/16 to 3/8 on recovery, the 9/16 slacked - trigger landed in bucket

Piston Corer Deck Log
(2500 lb)

SESAR IGSN #: ECS003003 3004

USGS ID: H-3-10-AR

Coast Guard ID: HLY1002

Date/Time 12 Aug 11:19 Z

Latitude 70 57.546

Longitude 144 03.143

Wire Out 1118 m

Scope 16'

Purpose Line 720 upper outcrop

Depth 1157 m

Observer BDE

Pull out 90000 lbs

Base weight 4400 tension

Piston Core ECS003003

Core ID 2P-1

Max Recovery ~~292 cm~~ 302 cm

Trigger Core ECS003004

Core ID 2TC-1

Max Recovery 0-79

Mud Line

5m

0

62

62 cm

90 cm

152 ~~142~~

150 cm

302 ~~292~~

0 cm

Catcher (CA)

Cutter(CC)

CA3

CA1/2

Cut Points

S1	☑	Section 1 0-62
S2	☑	Section 2 62-~~142~~ 152
S3	☑	Section 3 ~~142-292~~ 152-302
S4	☐	Section 4
S5	☐	Section 5
S6	☑	Section 6
CA	☑	Core Catcher (3)*
CC	☑	Core Cutter (2)
MFx	☑	Microfauna (ext)
GG	☐	Gas (geochem)
	☐	

Mud Line

Catcher (CA)

Cutter(CC)

Cut Points

S1	☑	Section 1
~~S2~~	☐	~~Section 2~~
CA	☑	Core Catcher (2)
CC	☑	Core Cutter
MFx	☑	Microfauna (ext)
	☐	

CC Undamaged, No dents

*CA 1+2 are stratigraphically equivalent CA3 is stratigraphically shallower

Sediment in CA is very stiff - removal of CA pulled plug out of barrel (sample CA3) CA 1+2 firmly held in CA, cut from same piece.

*Measurements on deck from bottom of core

Breakaway piston 27cm from top of core

Brief Textural Description

Other Comments

Piston Corer Deck Log
(2500 lb)

SESAR IGSN #: ECS 0003005
ECS 0003006
USGS ID: H-3-10-AR

Coast Guard ID: HLY1002

Date/Time 25 Aug 2010 / 1046 Local 1746 Z

Latitude 87° 34.72933 } Reconstructed from Log
Longitude 134° 28.62372 }

Wire Out 3009 m

Scope 16'

Purpose Date, Seamount 2009

Depth 3070 m

Observer _____

Piston Core ECS 3005

Core ID 3P-1

Max Recovery _____

Mud Line

Cut Points

546 cm
Actual 0 cm E
Top of Core
76cm
40cm
80 C 120cm
200 B 144cm
344 A 150cm
Contact (418cm)
494 cm D

S1	☐	Section 1
S2	☐	Section 2
S3	☐	Section 3
S4	☐	Section 4
S5	☐	Section 5
S6	☐	Section 6
CA2	☑	Core Catcher (in sleeve)
CC	☑	Core Cutter
MFx	☑	Microfauna (ext)
GG	☐	Gas (geochem)
Top (Ext)	☑	outside core barrel top of cc (~496cm) Also for MFx

See other side

CA1 ☑ end exit (bag)

Catcher (CA)

Cutter(CC)

*Field measurements from bottom of barrel.

Piston 33cm above mud. line

Trigger Core ECS 3006

Core ID 3TC-1

Max Recovery _____

Mud Line

Cut Points

S1	☐	Section 1
S2	☐	Section 2
CA1	☑	Core Catcher
CC	☐	Core Cutter
MFx	☐	Microfauna (ext)
	☐	

No CC

CA2 ☑

CA1 is bottom

CA2 is top

Catcher (CA)

Cutter(CC)

Brief Textural Description Liner imploded from 207 - 232cm

Bottom of Core
Yellowish orange sticky, silty clay w/ granules of same (granular silty clay clasts)

*** Sample D is in Ziplock Bag

Other Comments C: 130 - 149 cm gap (core disturbed) - contains plastic liner from below?

344 cm

A: Contact at 418cm from Top of Core (74cm from top of Section A)

Piston Corer Deck Log
(2500 lb)

SESAR IGSN #: ECS003007 3008

USGS ID: H-3-10-AR

Coast Guard ID: HLY1002

Date/Time 31 Aug 2010

Latitude 75 35.048

Longitude 140 05.576

Wire Out 3591 wire tension 8300

Scope ~~11~~ 17' pullout 10800

Purpose Distal Submarine Fan Channel site M02

Depth 3700

Observer BDE/CS

on deck & secured 1254 hrs

Piston Core

Core ID 4P-1 ECS003007

Max Recovery _____

25' Mud Line (on weight stand)

2 pipe

Cut Points

S1	☑	Section 1 0-87
S2	☑	Section 2 87-187
S3	☑	Section 3 187-337
S4	☐	Section 4
S5	☐	Section 5
S6	☐	Section 6
CA	☑	Core Catcher
CC	☐	Core Cutter
MFx	☑	Microfauna (ext)
GG	☐	Gas (geochem)
	☐	

C — 100 cm

B — 150 cm

A — 0

Catcher (CA)

Cutter(CC)

No Core Cutter sample

Trigger Core

Core ID 4TC-1 ECS003008

Max Recovery _____

Mud Line 100 cm

Cut Points

S1	☐	Section 1
S2	☐	Section 2
CA	☑	Core Catcher
CC	☐	Core Cutter
MFx	☐	Microfauna (ext)
	☐	

Ball of sed in CA - otherwise clean.

Catcher (CA)

Cutter(CC)

Brief Textural Description

Other Comments

- not a clean hit: bounce? / fall over?
- Trigger wire wrapped around 9/16 wire
- Piston was all the way up the liner
- Primarily a Gravity Core

Piston Corer Deck Log
(2500 lb)

SESAR IGSN #: ESC003009
3010

USGS ID: H-3-10-AR

Coast Guard ID: HLY1002

Date/Time 02 Sept 2010 / 18136Z

Latitude 76° 32.626

Longitude -128° 37.647

Wire Out 2015

Scope 16' - Loop tied up on main wire

were wt ~5-800 #'s
pullout ~8240 #'s
⇒ 2400 # @ pullout

Purpose Site of opportunity (wp 37

Depth 2061

Observer _____

Piston Core ESC003009

Core ID 5P-1

Max Recovery _____



Trigger Core ESC003010

Core ID 5TC-1

Max Recovery _____



Brief Textural Description

Other Comments

waiting for LSSL
Fog 1/2 mile vis; 9/10 ice

@ 2010 strange decrease in wt
no hard abrupt drop