

Base from U.S. Geological Survey digital data,
National Agriculture Imagery Program 2009
Universal Transverse Mercator projection, Zone 13

0.08 0.04 0 0.08 0.16 MILE
0.1 0.05 0 0.1 0.2 KILOMETER

Figure 27. Flood inundation map for a simulated dam breach at McGinnis Lake from a 100-year, 24-hour inflow design flood in six stream reaches (*A*), (*B*), (*C*), (*D*), (*E*), and (*F*), east to northwest.