U.S. Department of the Interior
U.S. Geological Survey

Prepared in cooperation with the
Virginia Department of Environmental Quality

Scientific Investigations Report 2017–5041
PLATE 2 of 2

McFarland, E.R., 2017, Hydrogeologic Framework and Hydrologic Conditions of the Piney Point Aquifer in Virginia







EXPLANATION

Borehole resistivity log—Heading in red indicates lithologic control from core and in blue from detailed cuttings descriptions. Heading in black indicates only driller's log or no lithologic information available





Location of hydrogeologic sections

Hydrogeologic Sections *A–A′*, *B–B′*, and *C–C′* of the Piney Point Aquifer in Virginia

By
E. Randolph McFarland
2017