





U.S. GEOLOGICAL SURVEY
DENVER
AUG 25 1986
LIBRARY
DIVISION

Mapped by W. A. Bowes,
E. M. MacKevett, Jr., and
L. J White, 1955

EXPLANATION

Kig — Isabella granodiorite — CRETACEOUS

Fault, showing dip
(Dashed where approximately located)

Vertical fault

Fault, showing bearing and plunge of slickensides

Shear zone

Probable ore

Probable low-grade ore

Argillic alteration

Portal of adit

Inclined workings
(Chevrons point down)

Foot of winze

Head of winze

Winze extending through level

(5) Radioactivity, in mr/hr
(Underground background .04-.05 mr/hr.)

Figure 8. Composite plan, geologic maps, and geologic section of underground workings at the Kergon Mine

(200) T67r no. 698