


Figure 9.--Effect of wind speed and direction on simulated discharge at Briarcliffe Acres gage (02110755).