



Surface mooring plus hardware

current

temperature >

water clarity

temperature



**Figure 2-7k.** Schematic of moorings at site HB12.