

0350116510 CULLASAJA RIVER AT SECONDARY ROAD 1653 NEAR FRANKLIN, NC

LOCATION.--Lat 35°09'52", long 83°21'37", Macon County, Hydrologic Unit 06010202, at bridge on Secondary Road 1653, 1.8 mi southeast of Franklin.

DRAINAGE AREA.--91.1 mi<sup>2</sup>

PERIOD OF RECORD.--June 2000 to September 2003 (discontinued).

REMARKS.--Samples collected for the Upper Little Tennessee Sediment Study.

WATER-QUALITY DATA, WATER YEAR OCTOBER 2002 TO SEPTEMBER 2003

Date	Time	Bedload sediment discharge, tons/d (80225)	Bedload sediment, sieve diameter <.063mm percent (80226)	Bedload sediment, sieve diameter <.125mm percent (80227)	Bedload sediment, sieve diameter <.25mm percent (80228)	Bedload sediment, sieve diameter <.5 mm percent (80229)	Bedload sediment, sieve diameter <1 mm percent (80230)	Bedload sediment, sieve diameter <16 mm percent (80234)	Bedload sediment, sieve diameter <8 mm percent (80233)	Bedload sediment, sieve diameter <4 mm percent (80232)	Bedload sediment, sieve diameter <2 mm percent (80231)
MAR 20...	1309	4.8	0.0	2	24	73	90	100	98	96	94
MAY 06...	1156	8.0	0.0	2	24	78	89	100	97	94	92