

## LC 58

**STAMPING** LC 58 1977  
**USGS QUAD MAP** CRYSTAL FALLS (1986)  
**NGS PID** PY0834

**LATITUDE** 44.71676  
**LONGITUDE** -110.50526  
**ELEVATION** 2398 m

---

### DATE OF DESCRIPTION 2003

**DESCRIPTION** Proceed 2.65 km (1.65 mi) south along the Canyon-Lake highway from the junction in Canyon Village. Bench mark is near the center of a 4- by 6-foot dome-shaped area of outcropping bedrock, 30.0 m (98.4 ft) west of the centerline of the highway, 9.1 m (29.9 ft) north of the center of a service road, and 1.5 m above the highway. The service road is the best indicator of the mark's location.



Looking northwest across highway at service road and bench mark (beneath person).



Close-up of bench mark.



Looking southwest across highway at service road and bench mark (beneath person).