

## CVO 84-8

**STAMPING** CVO 84-8  
**USGS QUAD MAP** LAKE (1986)  
**NGS PID** PY0858

**LATITUDE** 44.6225  
**LONGITUDE** -110.430556  
**ELEVATION** 2356 m

---

**DATE OF DESCRIPTION** 2003

**DESCRIPTION** Proceed 8.75 km (5.45 mi) north along Lake-Canyon highway from the junction of the East Entrance highway at Fishing Bridge. Bench mark is in top of, and 0.4 m (1.3 ft) northwest of, the southeast end of the southwest headwall of a stone culvert, 6.0 m (19.7 ft) southwest of the centerline of the highway, and 0.3 m below the highway.

In 2003, the mark was confirmed destroyed. The headwall is badly damaged.



Looking at culvert and holes where marks used to be.