

LEWIS FALLS

STAMPING LEWIS FALLS 1987
USGS QUAD MAP LEWIS FALLS (1986)
NGS PID PY0813

LATITUDE 44.2674681
LONGITUDE -110.6345781
ELEVATION 2346 m

DATE OF DESCRIPTION 2002

DESCRIPTION Proceed 9.6 mi south along the south entrance highway from the junction of Grant Village entrance road. Bench mark is in the sidewalk of a bridge over the Lewis River (at Lewis Falls), set into a drill hole in the east sidewalk of bridge, 7.8 meters (25.6 ft) northeast from the southwest end of the sidewalk, 4.9 meters (16.1 ft) southeast from the approximate center of road, 0.4 meters (1.3 ft) northwest from the bridge railing, 0.2 meters (0.7 ft) southwest from a bridge expansion joint, and about 5 m north of mark "14-4 FHA."



Looking south from bridge along highway at bench mark (beneath yellow case).



Close up of bench mark.



Looking north along highway at bench mark (beneath yellow case), mark 14-4 FHA (in the foreground), and bridge.