STAMPING U 10 1923 8429.9 **USGS QUAD MAP** BEACH LAKE (1986) **NGS PID** PY0032 LATITUDE 44.5029 LONGITUDE -110.51731 ELEVATION 2595 m

DATE OF DESCRIPTION 2003

DESCRIPTION Proceed 2.1 mi southwest along the Lake-West Thumb highway from the junction of the Lake Village entrance road in Lake Village, thence 4.9 mi southwest along a service road (the old highway). Bench mark is in top of a dome shaped boulder that projects 22-inches above the ground surface, at a point where a utility line crosses the road, 29.0 m (95.1 ft) southwest of a utility pole, 6.1 m (20.0 ft) southeast of the center of the road, and above the level of the road.

In 2003, the mark was confirmed destroyed, since the boulder into which the bench mark was set has obviously been moved.



Disturbed boulder with mark in upper right.



Close up of bench mark.



Looking southeast across road at hole where boulder used to be and bench mark (near person).