



Figure 7.--Daily mean discharge for 2001 water year and median daily mean discharge for 1971-2000 water years for Lumber River at Boardman (02134500).