



EXPLANATION	
u200	Organic clayey silt
u100	Organic clayey silt
u80(b)	Orange silty clay
u70(cd)	Banded brown clays & silts
u63(g)	Dark brown clayey silt
u61(h)	Charcoal-rich sand
u50(i)	Banded organic silty clays with charcoal stringers
u45(k)	
u45(m)	
u45(o)	
u45(j-o)	Interbedded sands and clays
u41(p)	Dark brown clayey silt
u31(qr)	Dark brown clayey silt
u20(stu)	Yellow brown sandy silt
—	Contact—Dashed, approximate; dotted, inferred
E3	Event horizon
u80	Unit number
▲ [bulk]	Radiocarbon sample location—rectangle indicates bulk samples
(k)	Krotovina—infilled burrow
ABBREVIATIONS	
bsc	blocky scarp colluvium
cl	clay
gc	gray clay
gv	gravel
m	medium
sd	sand
st	silt
rk	rock

LOGS AND DATA FROM TRENCHES ACROSS THE HAYWARD FAULT AT TYSON'S LAGOON (TULE POND), FREMONT, ALAMEDA COUNTY, CALIFORNIA, 2001-2003

By

James J. Lienkaemper, Patrick L. Williams, Timothy E. Dawson,
Stephen F. Personius, Gordon G. Seitz, Samuel J. Heller, and David P. Schwartz

2003

This map was printed on an electronic plotter directly from digital files. Dimensional calibration may vary between electronic plotters and between X and Y directions on the same plotter, and paper may change size due to atmospheric conditions; therefore, scale and proportions may not be true on plots of this map.

Available on World Wide Web at
<http://pubs.usgs.gov/of/2003/of03-488/>

Any use of trade, firm, or product names in this publication is for descriptive purposes only and does not imply endorsement by the U.S. Government.