PREPARED IN COOPERATION WITH
ALASKA DIVISION OF GEOLOGICAL AND GEOPHYSICAL SURVEYS



UNDRAINED SHEAR STRENGTH PROFILES, LYNN ARY PARK, ANCHORAGE, ALASKA