



Figure 22. Photograph of the surface of a 41" subsurface float that was deployed at about 10 m below the surface (top) and tripod recovery floats that were deployed about 3 m above the bottom (bottom) between September 1988 and February 1999. Both floats were deployed without antifouling paint. Extensive barnacles grew on the lower floats during this time period, while only a thin layer of organic material grew on the upper float.