Pavillion, WY EPA well MW01 1
April 24, 2012

10:00 Depth to water 201.35
from top of casing

11:10 Pump on
~6 gpm

12:09
~~Elev~~ Pump rate reduced to
~2.6 gpm

13:05 Parameter stability
13:48 EPA sample 1
~~14:00~~ Start sampling
14:15 (delayed due to labeling
4 sets of sample bottles)
(further delay to ~~to~~ sync
w/ EPA sample 2)

Figure A3a. Field analysis notebook, page 1.