

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

34 H 337  
Washington TWS, PI  
File No. {  
District \_\_\_\_\_

T.W-5 Chlorides & Hardness

Depth (feet)	Chloride (ppm)	Hardness (ppm)	Remarks
1020	830	960	Air lift Reverse Circ
1040	810	920	
1060	760	910	
1080	1108	4180	
567-1080	1,100	1,500	Composite Free Flow ✓
1092	1,700	1,540	Air lift,
1112	<del>1,740</del> 2150	<del>2,150</del> 6,740	"
1133	1,540	1,580	"
1155	1,520	1,520	"
<del>1171</del> 1171	1,540	1,500	
1185	1,260	1,380	
<del>567-1185</del> 1185	<del>1,260</del>	<del>1,400</del>	
567-1192	1,460	1,420 x 2,	Free Flow Composite
* 1182-1200	320	550	Parker test.
1220	<del>620</del> 390	<del>390</del> 620	Bailed Sample
1240	300	480	"
1260	420	595	"
1187	396	<del>600</del>	Free Flow
1300	Not analyzed		
1280	- do -		
* 1282-1281	528	700	Free Flow
1281-1300	430	620	Parker test
1320	230	420	
1340	<del>460</del> 4 (checked)	630	
1360	<del>470</del> 64	244	
1380	<del>520</del> 410	614	
1385	520	638	
1385-1400	23	226	
1420	86	292	
1440	550	680	
1460	108	300	
1480	332	540	
567-1189	1,400	1,400	
1182-1500	180	440	
* 1187-1503	.		
1187-1503			