




SOLDIERS GROVE—Flood debris



Location of air photos shown on this sheet



UNRECTIFIED AERIAL PHOTOS  
TAKEN JULY 5, 1978  
SCALE APPROXIMATELY  
1:18,000 (1" = 1500')  
FLOOD DELINEATIONS BASED ON  
FIELD SURVEY AND  
LARGE SCALE TOPOGRAPHIC MAPS



SOLDIERS GROVE—Depth of floodwater on building




READSTOWN—Depth of floodwater at sewage treatment plant sign



SOLDIERS GROVE—Wis Highway 131 looking northwest



SOLDIERS GROVE—Right bank area of overflow from levee breach



SOLDIERS GROVE—Depth of floodwater on rear of Farmers' Cooperative building

**FLOOD OF JULY 1-5, 1978 ON THE KICKAPOO RIVER,  
SOUTHWESTERN WISCONSIN**

BY  
P. E. HUGHES, J. S. HANNUKSELA, AND W. J. DANCHUK  
1981