


11-61

PLATE 14A



LOG AND TEST RESULTS
BORING OAR-2A, OAK CRATER
ENEWETAK ATOLL, MARSHALL ISLANDS