

EXPLANATION

WELLS AND TEST HOLES

Well equipped with turbine pump

Well equipped with small pump

Well, unused

Well, oil-test

Test hole

CHEMICAL AND OTHER DATA

T=512

Depth of drill-stem test in test hole

R

Reported chemical analysis

Chloride (ppm) 512 ○ 385 Sulfate (ppm)

366.4 Depth to water

500 Depth of well

Measured depths given in feet and tenths.
Reported depths given in feet.

PLATE I.– Wells and test holes in the McGregor Range Area, Otero and Doña Ana Counties, New Mexico and El Paso County, Texas