




(200)
R290
no. 506



0 5 10 20 Ft.
Horizontal and Vertical Scale
Dashed piling 1947
Solid piling 1954
② Pile number
(Shortest pile in each bent plotted)

Fig. 17.--Geologic cross sections at bridge at Mile Post 456.7 in Goldstream Valley near

Fairbanks, Alaska. The Alaska Railroad.

This report is preliminary and has not been edited or reviewed for conformity with U.S. Geological Survey standards and nomenclature.