

(200)  
R290  
710.5061  
1959





Figure 19



LITHOLOGY, MOISTURE, AND TEMPERATURE DATA FROM DRILL HOLES AT THE ALASKA RAILROAD BRIDGE SITES AT MILE POSTS 456.7, 458.4, AND 460.4 IN GOLDSTREAM VALLEY NEAR FAIRBANKS, ALASKA

This report is preliminary and has not been edited or reviewed for conformity with U.S. Geological Survey standards and nomenclature.