

(200)  
R2910  
no. 5061  
1959

PLEASE REPLACE IN POCKET  
IN BACK OF BOUND VOLUME





Fig. 22.--Geologic cross sections at bridge at Mile Post 458.4 in Goldstream Valley, Fairbanks, Alaska  
The Alaska Railroad

This report is preliminary and has not been  
edited or reviewed for conformity with U.S.  
Geological Survey standards and nomenclature.