


(200)
R290
no. 5061
1959



PLEASE REPLACE IN POCKET
IN BACK OF BOUND VOLUME




Fig. 25.--Geologic cross section at bridge at Mile Post 460.4 over
Goldstream Creek near Fairbanks, Alaska

The Alaska Railroad

This report is preliminary and has not been
edited or reviewed for conformity with U.S.
Geological Survey standards and nomenclature.