



Figure 4.-- The water stage in Lake McMillan, the water level in well 20.26.17.334, and the discharge of the Pecos River at damsite 3 gaging station when there is no flow from Lake McMillan, 1957-64, Eddy County, N. Mex.