

(200)  
R29c  
no. 864  
plates

65-179






FIG.14 TEST TRENCH F AND GULLY C-MAPS OF WALLS