

(200)  
R 290  
no. 945



32  
Figure 32.--Incipient slump block on the northeast side of Grand Mesa. Slump is on the left.

PLEASE REPLACE IN POCKET  
IN BACK OF BOUND VOLUME




Figure 33.--Recent opening of fracture in basalt on west end of Grand Mesa. Slump is on the right.