

68-138





Figure 22.--Water levels during drawdown and recovery water levels and rate of discharge during performance test of well 21.4.22.222, Hazardous Test Area, White Sands Missile Range, N. Mex., October 13-14, 1960.