


EXPLANATION
Data point
—20—
Lines of equal saturated thickness,
in feet, March 1968
Project boundary

Base from U.S. Geological Survey
1:24,000 Photos 1951, Hill 1951, Proctor 1953, Wild Horse Lake 1951,
Alwood NE 1951, Sterling North 1951, Sutter 1950, Liker Ranch 1952,
Wilford 1951, Alwood 1951, Sterling South 1951, Reardon Hill 1951



MAP SHOWING SATURATED THICKNESS OF THE VALLEY-FILL AQUIFER IN THE STERLING REACH OF THE SOUTH PLATTE RIVER VALLEY, COLORADO, MARCH 1968
By
Paul A. Schneider, Jr.,
1972