

(200)
R290
no. 76-62




FIGURE 11.-Geophysical logs of the Castle Hills test hole, AY 68-28-910