

(200)  
R290  
no. 76-627




FIGURE 7.-Geophysical logs of the San Marcos test hole, LR 67-09-110