



Note: Observed wells appear to be measurable and capable of yielding water samples, but were not examined for such. Some destroyed wells may be capable of rehabilitation. Location of wells is approximate.

Fig. 11. Location and alignment of trenches and location of wells in Burial Ground 5-South (from Oak Ridge National Laboratory Engineering Drawing C-20923-EA-002-E)