

**EXPLANATION**

- 266 Observed well
- III Damaged or destroyed well
- ▨ Trench
- Topographic contours
- - - 775 - - - Contour interval, 5 ft.
- - - - - Contour interval, 1 ft.
- - - II - - - Contours showing depth to water, April 22, 1965




Fig. 13. Location and alignment of trenches and location of wells in Burial Ground 6, as of June 1974 (from Oak Ridge National Laboratory Engineering Drawing No. C-10822-FA-006-D)

WHITE OAK LAKE