




Figure 6.--Temperature, dissolved-oxygen concentration, and specific-conductance profiles at site 1 in Flaming Gorge Reservoir.