

(200)
R290
28-78-412



Figure 13.--View of the San Carlos Reservoir looking southwest. The San Carlos River enters the reservoir just beyond the ridge extending across the right center of the photograph. Note the off-channel ponds. The channel of the Gila River has been plugged (arrow). The elevated ridge parallel to the leading edge of the airplane wing (left center) is the fill for the approaches to an abandoned railroad bridge. Photographed April 20, 1965.