

(200)
R29
no 74-678



Prepared by the U.S. Army Topographic Command (AJAM), Washington, D.C. Compiled in 1954 by photogrammetric methods from aerial photographs taken 1953. Photographs field annotated 1953. Revised in 1973 by the U.S. Geological Survey from aerial photographs taken 1972.

CONTOUR INTERVAL 50 FEET
WITH SUPPLEMENTARY CONTOURS AT 25 FOOT INTERVALS

Figure 11.--Area subject to flooding along the Sabine River after 25-percent dam failure during 100-year flood.