




Figure 21.--Water levels in two wells finished in the Navajo Sandstone near Calneville, 1974-77.

(200)
R290
no. 79-1163