

Table 5.--Continued

Location	Owner	Year constructed	Depth of well (feet)	Casing diameter (inches)	Depth of casing (feet)	Depth to first perforations (feet)	Altitude
(C-3-5)4abd-1	A. Castagno	1975	-	-	-	-	4,325
4bbb-2	V. Fawson	1957	410	12	407	195	4,311.2
5aba-1	L. Johnson	1953	412	10	412	117	4,304
5ada-1	J. Boyer	1953	350	6	345	234	4,318
7abc-1	P. Matthews	1954	390	16	390	150	4,433
7cca-1	U.S. Geological Survey	1978	1,524	8	113	-	4,515
7dcc-1	J. Millyard	1956	395	16	289	205	4,508
22dab-1	U.S. Army, Tooele Depot	1978	1,492	6	428	375	4,553
36ddd-1	do.	1942	763	20	752	392	4,848.1
(C-3-6)1bdb-1	North Willow Irrigation Co.	1954	418	16	418	238	4,454
36aac-1	U.S. Army, Tooele Depot	1955	780	12, 10	780	638	5,015

Test hole augered for this investigation by U.S. Geological Survey; destroyed.