

(200)
R290
no 80-557





Figure 7.-- Comparison of pumpage at Haven well and water levels in nearby test holes