

EXPLANATION:

Fault; dashed where inferred; dotted where buried; ball and bar on downthrown side

Linear break in slope; dashed where less distinct; circle and bar on lower side

Lineament identification number

Tr. LC-1 Trench location

Topographic profile

0 0.5 1 kilometer

This map is preliminary and has not been reviewed for conformity with U.S. Geological Survey editorial standards and stratigraphic nomenclature. Any use of trade names is for descriptive purposes only and does not imply endorsement by the USGS.

Project No. 14093B

USGS Contract No. 14-08-0001-16827

Woodward-Clyde Consultants

MAP OF FAULT TRACES AND LINEAMENTS Little Cottonwood Canyon Site

Figure 6