


Aerial photography by Merrick and
Company, May 1980



AERIAL PHOTOGRAPH SHOWING OUTLINE OF STUDY AREA AND LOCATION OF RAIN GAGES AND MONITORING SITE FOR ROONEY GULCH AT ROONEY RANCH, NEAR MORRISON, COLORADO