



Aerial photography by Merrick and
Company, May 1980

AERIAL PHOTOGRAPH SHOWING OUTLINES OF STUDY AREA AND SUBCATCHMENTS, LOCATION OF RAIN GAGES AND MONITORING SITES FOR ASBURY PARK STORM DRAIN AT DENVER, AND
ASBURY PARK STORM DRAIN AT ASBURY AVENUE, AT DENVER, COLORADO