




Aerial photography by Merrick and
Company, May 1980



**AERIAL PHOTOGRAPH SHOWING OUTLINES OF STUDY AREA AND SUBCATCHMENTS, LOCATION OF RAIN GAGES AND MONITORING SITES FOR
NORTH AVENUE STORM DRAIN AT DENVER FEDERAL CENTER, AT LAKEWOOD, AND NORTH AVENUE STORM DRAIN AT
DENVER FEDERAL CENTER NORTH AVENUE, AT LAKEWOOD, COLORADO**