



Aerial photography by Merrick and Company, May 1980

AERIAL PHOTOGRAPH SHOWING OUTLINES OF STUDY AREA AND SUBCATCHMENTS, LOCATION OF RAIN GAGES AND MONITORING SITE FOR STORM DRAIN AT 116TH AVENUE AND CLAUDE COURT, AT NORTHGLENN, COLORADO