




- EXPLANATION**
- 394236  
1050424 ▲ U.S.G.S. MONITORING SITE AND IDENTIFICATION NUMBER
  - ◆ RAIN GAGE
  - - - STUDY AREA
  - 1 - SUBCATCHMENT BOUNDARY AND NUMBER
  - 24 - GUTTER OR PIPE AND NUMBER

Aerial photography by Merrick and Company, May 1980



**AERIAL PHOTOGRAPH SHOWING OUTLINES OF STUDY AREA AND SUBCATCHMENTS, LOCATION OF RAIN GAGE AND MONITORING SITE FOR VILLA ITALIA STORM DRAIN AT LAKEWOOD, COLORADO**