



Plate 1. Map of active part of the Slumpgullion landslide, showing surface structures as appeared in the summer of 1991. Stations, in meters, shown for reference to structures cited in text.

By  
R. Guzzi and M. Parise  
1992

This report is preliminary and has not been reviewed for conformity with U.S. Geological Survey editorial standards. Any use of trade, product, or firm names is for descriptive purposes only and does not imply endorsement by the U.S. Government.