U.S. DEPARTMENT OF THE INTERIOR
U.S. GEOLOGICAL SURVEY

PREPARED IN COOPERATION WITH THE
FEDERAL EMERGENCY MANAGEMENT AGENCY

OPEN FILE REPORT 94-116
Lake Ingraham east quadrangle-PLATE 15
Murray, M. H., 1994, Storm-tide elevations produced by Hurricane Andrew along the southern Florida coasts, August 24, 1992

Mapped, edited, and published by the Geological Survey

Control by USGS and USC&GS

Orthophotomap prepared from aerial photograph taken January 16, 1971
Topography by planetable surveys 1972. Field checked 1972

Selected hydrographic data compiled from USC&GS Chart 598 SC (1972)
This information is not intended for navigational purposes

UTM GRID AND 1972 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET

SCALE 1:24 000

CONTOUR INTERVAL 5 FEET
NATIONAL GEODETIC VERTICAL DATUM OF 1929
DEPTH CURVES AND SOUNDINGS IN FEET—DATUM IS MEAN LOW WATER
THE MEAN RANGE OF TIDE IS APPROXIMATELY 2.9 FEET

THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS

INTERIOR—GEOLOGICAL SURVEY, RESTON, VIRGINIA—1976

ROAD CLASSIFICATION
Trails

LOCATION

LAKE INGRAHAM EAST, FLA.
N2507.5—W8100/7.5
1972

PLATE 15.--MAP SHOWING WATER-SURFACE ELEVATIONS AND HIGH-WATER MARK LOCATIONS IN AREAS AFFECTED BY HURRICANE ANDREW, LAKE INGRAHAM EAST, FLORIDA, QUADRANGLE.