





QUADRANGLE LOCATION

MAP SHOWING HIGH-WATER MARKS, CONTINUOUS GAGING STATIONS, AND WATER-SURFACE ELEVATIONS OF STORM-TIDE INUNDATION
CAUSED BY HURRICANE ANDREW, AUGUST 25-27, 1992: PORT ARTHUR, TEXAS, LOUISIANA QUADRANGLE